



NEW LANTAO BUS Co. (1973) LTD.
新大嶼山巴士(一九七三)有限公司

冠忠巴士集團有限公司附屬公司 A Subsidiary of Kwoon Chung Bus Group

3 July 2013

Mr. Joan Albert Ferrer
Asis Manager
Ronser Polarizer Device

Dear Sir,

After over one and a half year running with Ronser Polarizer Device on two of our buses BM3218 and MG9594, we hereby certify that there were no mechanical problem occurred because of this device during the abovesaid period.

Thank you.

Should you have any query, please contact me at phone no.
29848361

Yours faithfully,
For and on behalf of
New Lantao Bus Co. (1973) Ltd.

WONG Wah
Administration Manager